


Technical Service Bulletin

Drill Hole Pattern for Standard Housing Actuators June 18, 2012



- Model 66/660/660E requires 2 - 1/2" x 4" Grade 5 bolts with lock washers (not included)
- Other Model Actuators requires 3 - 1/2" x 4" Grade 5 bolts with lock washers (not included)
- All TIE DOWN ENGINEERING standard actuators have the same hole pattern for consistent hole placement

Instruction Sheet #08074

TIE DOWN ENGINEERING • 255 Villanova Drive SW • Atlanta, GA 30336
www.tiedown.com (404) 344-0000 Fax (404) 349-0401



CS09, 080116